Questions? Call toll free: 888-783-2612

MAINS CONNECTION

In a double-insulated appliance, two systems of insulation are provided instead of grounding. No grounding means is provided on double-insulated appliance, nor should a means for grounding be added to the appliance. Servicing a double-insulated appliance requires extreme care and knowledge of the system, and should only be carried out by qualified service personnel. Replacement parts for a double-insulated appliance must be identical to the parts they replace. This double-insulated appliance is marked with the DOUBLE-INSULATED symbol.



Intertek 3077193 FORMS TO UL STD.1450

CONFORMS TO UL STD.1450 CERTIFIED TO CSA STD. C22.2 NO.68-09

Design Registrations:

GB 2106529 DE 402 04 314.6 FR 02 3314 US D488,169S

Spray Gun Design Registration:

GB 3006933

Copyright & Design Right Reserved © 2013

EARLEX INC WILL ACCEPT NO RESPONSIBILITY FOR THE USE OF THIS PRODUCT IF USED FOR ANY PURPOSES OTHER THAN THOSE DETAILED HEREIN.

WARRANTY

This product is guaranteed for a period of 24 months against faulty manufacture and materials. It is not guaranteed for industrial or hire purposes. The guarantee does not affect your statutory rights. Earlex Inc will accept no responsibility for the use of this product if used for any purposes other than detailed herein.

PLEASE NOTE: We have done all we can to ensure that used, correctly and according to these instructions, this Spray Station will give a long and trouble- free life. We accept no responsibility for damage caused by the use of incorrect or unsuitable substances, paints or fluids which have not been thinned correctly or are unsuitable for the surfaces to which they are applied, health hazards arising from lack of ventilation when working in confined spaces or failure of the equipment due to inadequate cleaning of the components after use. If in doubt, always test a small inconspicuous area first. Always read the paint manufacturer's instructions first. Neither our warranty nor the above statement affects your statutory rights.

Questions? Call toll free: 888-783-2612



8261 Highway 73, Suite F, Stanley, N.C. 28164, USA Earlex Inc, Toll Free 888-783-2612

Email: questions@earlex.com Website: www.earlex.com