

JWS-35X3-1 SHAPER 3HP, 1PH

708323

This heavy-duty JET Shaper is available with a powerful 3HP, 1Ph motor with magnetic controls. The four-speed (4000, 6000, 8000, 10000 RPM) step pulley drive with quick release lever allows you to select the best speed and torque for different cutter diameters. The spindle is reversible, and receives maximum power transfer from the v-belt. The independently adjustable fences have micro adjust controls for precise positioning.



FEATURES

- Four-speeds 4000, 6000, 8000, 10000 RPM let you select the best speed and torque for different cutter diameters
- Powerful 3HP, 1Ph motor with magnetic controls
- Poly-V-belt transfers maximum power to the spindle
- Large 26-3/4" X 32-1/4" precision ground cast iron table provides a durable work area, predrilled for power feeder
- Spindle height scale
- Starting pins for irregular shaping
- Extruded aluminum fence comes with T-Slots and 2 feather board hold-downs
- Extra-large chrome handwheel is conveniently located for fast, easy and accurate spindle height adjustments
- Reversible spindle speeds for diverse shaping jobs
- 4" Dust port built into fence for convenient hookup to any dust collection system
- Spindle lock for safe and easy cutter set-up



JET RED ASSURANCE 5-YEAR WARRANTY

JET warrants every product it sells. If one of our tools needs service or repair, one of our Authorized Service Centers located throughout the United States can give you quick service. In most cases, any of these JPW Industries Authorized Service Centers can authorize warranty repair, assist you in obtaining parts, or perform routine maintenance and major repair on your JET tools. For the name of an Authorized Service Center in your area call 1-800-274-6848.

STAND BEHIND YOUR WORK™



550+ SERVICE CENTERS NATIONWIDE

INDUSTRY-LEADING WARRANTIES

EXPERT TECHNICAL SERVICE

JWS-35X3-1 SHAPER 3HP, 1PH

708323

SPECIFICATIONS

Spindle Speed (RPM)	4000/6000/8000/10000
Maximum Spindle Diameter (In.)	1-1/4
Spindles Included	1-1/4"
Spindle Size Under Nut (In.)	4
Spindle Travel (In.)	4
Reversible	Yes
Maximum Diameter Cutter Above Table (In.)	7-1/2
Maximum Diameter Cutter Below Table (In.)	6
Table Opening Diameter (In.)	6-19/64
Table Inserts (In.)	2
Table Insert Opening Diameter (In.)	2-9/16, 4-5/16
Table Size (L x W) (In.)	32-1/4 x 26-3/4
Table T-Slot (In.)	3/4 x 3/8
Table Height from Floor (In.)	33-1/4
Fence Size (L x H) (In.)	16 x 4-3/4
Fence Travel (Major and Minor) (In.)	4, 1
Dust Port Outside Diameter (In.)	4



STAND BEHIND YOUR WORK™



550+ SERVICE CENTERS NATIONWIDE

INDUSTRY-LEADING WARRANTIES

EXPERT TECHNICAL SERVICE