




**NORTH AMERICA HAS  
MORE THAN 15,000  
DRYER FIRES A YEAR!**



**LintAlert® DRYER SAFETY ALARM**

**EVERY DAY MORE THAN 50 DRYERS CATCH FIRE IN NORTH AMERICA**

Lint makes it past the filter and collects in every dryer's exhaust system. The result: longer drying times that waste energy and wear out clothes. Most importantly, exhaust problems also create a very real fire danger. Today, you can help save energy and improve your home's safety.

The LintAlert® should be added as part of every home safety plan, which includes smoke and carbon monoxide detectors and fire extinguishers.

The Lint Alert is easy and quick to install. It attaches to your dryer's exhaust hose (on the back of the machine). The LintAlert® measures the pressure changes that occur as the dryer is used. As lint naturally builds up over time or as a result of any other blockage in the vent or the exhaust exit point, LED indicators progressively illuminate to show how efficiently the dryer is exhausting. If airflow restriction becomes dangerous, an audio / visual alarm is triggered to let you know that the dryer needs attention



- DETECTS EXHAUST PROBLEMS BEFORE THERE IS A DANGER
- HELPS PREVENT DRYER FIRES
- INDICATES WHEN IT IS TIME FOR PREVENTATIVE MAINTENANCE
- REDUCES DRYING TIME & HELPS SAVE ENERGY BY ENSURING PROPER VENTING
- LENGTHENS APPLIANCE LIFE