

## Opening CT6101 Battery Compartment



1. Hold tester in middle of body.
2. Twist strain relief at base of tester counter-clockwise to loosen.
3. Insert batteries in orientation indicated on tester.