

INSTRUCTIONS

- Soak in cold water 10-15 minutes (do not over-hydrate)
- Ring out excess water and distribute crystals evenly within channels
- Wear around neck or head, rotate occasionally for cooling boost
- Re-soak or refrigerate to re-cool and reuse. DO NOT freeze.