

HOW TO MEASURE WINDOW TREATMENTS

For all measurements, use a steel tape measure.



Horizontal Blinds:

1 Choose Mount Type




Inside Mount window treatments are installed inside the window casing.




Outside Mount window treatments are mounted outside the window casing and provide better privacy. Mount directly on the wall or to the window molding.

2 Measure



For **inside mounts**: Measure the inside of the window frame in **3 places** for width and height.



For **outside mounts**: Measure the **overall area** to be covered.

3 Record Measurements

For **inside mounts**: Record the narrowest width and longest height.

For **outside mounts**: Add extra inches (approximately 3") to the width and height for optimum light control and privacy.