



## Replacement Parts List

# Replacement Parts



Mfg Item	Description	Cost	MSRP
RP001	Replacement 5 Gallon Tether/Spout Cap & Back Cap	\$3.97	\$7.97



Mfg Item	Description	Cost	MSRP
RP002	Replacement 2.2 Gallon Tether/Spout Cap & Back Cap	\$3.97	\$7.97



Mfg Item	Description	Cost	MSRP
RP003	Replacement Thumb Button Assembly (Valid for 2.2 Gal/5 Gal)	\$3.97	\$7.97



Mfg Item	Description	Cost	MSRP
RP004	Replacement Spout Assembly (Valid for 2.2 Gal/5 Gal)	\$3.97	\$7.97

### CERTIFICATIONS

