

SINGLE-GANG BLANK COVER
Cubierta Ciega Sencilla
Couvercle Universal Simple



GENERAL INSTRUCTIONS

1. Turn off power.
2. Center cover gasket evenly.
3. Install mounting screws (provided).
4. Use caulking around cover if not mounted to a U.L. listed wet locations box.

LISTED 22F0
FLUSH DEVICE COVER
WET LOCATIONS

LISTADA 22F0
TAPA PARA
DISPOSITIVO AL RAS
SITIOS MOJADOS

ENREGISTRER 22F0
COUVERCLE DE
DISPOSITIF AFFLEURANT
ENDROITS MOUILLES



INSTRUCCIONES AL DORSO
INSTRUCTIONS AU DOS

HUBBELL ELECTRICAL PRODUCTS
DIVISION OF HUBBELL INCORPORATED (DELAWARE)
P.O. BOX 4002 SOUTH BEND, INDIANA 46634
CANADA: 870 BROCK RD., S. PICKERING, ON L1W 1Z8
MADE IN INDIA / HECHO EN INDIA / FAIT DANS L'INDE

5173-0



0 50169 51730 7

INSTRUCCIONES GENERALES

1. Cortar la corriente
2. Centrar bien la junta en la tapa. Colocar los tornillos de fijación (provistos).
3. Aplicar un sellador alrededor de la tapa si no está fijada a una caja homologada por U.L. para lugares mojados.

DIRECTIVES GÉNÉRALES

1. Couper le circuit d'alimentation.
2. Centrer correctement la garniture de joint du couvercle. Monter les vis de fixation (fournies)
3. Placer du calfeutrage autour du couvercle si celui-ci n'est pas monté sur une boîte homologuée U.L. pour les endroits mouillés..