

TUBE PIPE INSULATION

1. Measure length of pipe to be insulated and cut insulation to length
2. Cut insulation at a 45 degree angle to cover any elbows in the pipe.
3. Open insulation along pre-cut slit and slide around pipe.
4. Apply a length of tape over slit in insulation to complete the project.

