





OK-5109H

ASSEMBLY INSTRUCTION

INDOOR USE ONLY

Assembly steps:

Step 1. Hang Beads (D) on the Hole (A4).

Step 2. Pass main Wire (O) through Tube (B).

Step 3. Attach Tube (B) to Connector (A1), take out Nut (B1), put Assembly (C) over Tube (B), and secure with Nut (B1), adjust Assembly (C) on proportion position.

Step 4. Position the glass dish(P)over the threaded tube,put the block washer(Q)onto the threaded tube,and secure with the nut(R),position candle sleeve over the lamp holder(S)

Step 5. Hang Beads (F), put Ring (F1) into Ring (C2), put Ring (F2) into Ring (A3). Hang Beads (E), put Ring (E1) into Ring (C2), put Ring (E2) into Ring (A2).

Follow the same method as step 4 to hang all the beads strings (total 12pcs)

Step 6. Mount Shade (G) to Tube (B) and secure with Loop (H).

Step 7. Turn in Bulbs to Lampholders.

Step 8. Mount the Ceiling fitting:

Step 8-1. Tighten Loop (J) on Tube (K).

Step 8-2. Loosen Screw (N) and pass Canopy (L) over Tube (K).

Step 8-3. Tighten Loop (M) on Tube (K).

Step 8-4. Pass main Wire (O) through Links of Chain (I), Loop (J), Canopy (L), Tube (K) and Loop (M).

Step 8-5. Open and attach first Link and last Link of Chain (I) to Loops (H) and (J), and use Plier to close Links of Chain.

Step 8-6. Connect Wire (O) to the power supply Cord.

Step 8-7. Raise Canopy (L) to the Ceiling and secure it by tightening Screw (N).

Step8-8. Hang Loop (M) on the Hook on the Ceiling.

After complete the above instruction, please check once more to ensure its safety. Then you can turn the power on. If the external cord is damaged, please have it fixed by a qualified person to avoid hazard.