
ASSEMBLY INSTRUCTION

ITEM NO.:K6909



PARTS IDENTIFICATION

HARDWARE IDENTIFICATION

1		1PC	2		1PC	A	Φ 6*12mm	12PCS	В	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	4PCS
3	right	1PC	4	left	1PC	С	4mm	1PC			
5		1PC	6		2PCS	ATTENTION.					

bottom

ATTENTION:

WHEN YOU ASSEMBLE, PLEASE I SCREW UNTIL ALL SCREWS ARE LINI