


NuMax – SBR50



Wearing Parts:

Ref. NO.	Name	Size	Total Quantity
10	O-Ring	9.5×2.65	1
12	O-Ring	31.5×2.4	1
16	O-Ring	21×3	1
17	Piston		1
18	Pin		1
19	Driver Blade		1
26	Bumper		1
28	Nozzle		1
32	O-Ring	3.5×1.5	1
38	O-Ring	1.8×1.8	1