


**RECTANGULAR CLUSTER  
COVER**  
**Cubierta Rectangular Sencilla**  
**Couvercle Rectangulaire**



**GENERAL INSTRUCTIONS**

1. Turn off power.
2. Use only copper wire.
3. Remove appropriate device cutout on gasket.
4. Center cover gasket evenly.
5. Install mounting screws (provided).
6. Use caulking around cover if not mounted to a U.L. listed wet locations box.
7. Installation and wiring must comply with local electrical codes.



One Outlet 1/2"  
Una Salida 1/2"  
Une Prise 1/2"

Follow mounting and wiring instructions furnished with lampholder(s).

Seguir las instrucciones de fijación y cableado que acompañan a el (o los) portalámparas.

Suivre les directives de montage et de câblage fournies avec le lampadaire.

LUMINAIRE FITTING  
WET LOCATIONS  
MONTAJE PARA LAMPARA  
SITIOS MOJADOS  
LUMINAIRE AJUSTER  
ENDROITS MOUILLÉS



INSTRUCCIONES AL DORSO  
INSTRUCTIONS AU DOS

HUBBELL ELECTRICAL PRODUCTS  
DIVISION OF HUBBELL INCORPORATED (DELAWARE)  
P.O. BOX 4002 SOUTH BEND, INDIANA 46634  
CANADA 870 BROCK RD. S. PICKERING, ON L1W 1Z8  
MADE IN INDIA / HECHO EN INDIA / FAIT DANS L'INDE

**5186-0**

