

## **DEFT WOOD TOUCH-UP/REPAIR/RESTORATION COLORLESS WOOD COATING**

**WHERE TO USE:** This aerosol has the advantages of spray application, great flow, and is convenient for hard-to-brush areas without the expense and laborious clean-up of spray equipment.

**COVERAGE:** 60 square feet per can.

**SURFACE PREPARATION:** Clean surface thoroughly, sand with fine 220 sandpaper. Remove all dust with rags soaked in acetone. Test in a small area. If previous finish wrinkles or lifts, strip to bare wood.

**APPLICATION:** Cover nearby surfaces, provide adequate ventilation, eliminate ignition sources, and wear safety glasses. Shake the can for 1 minute. Spray 6-10 inches from surface. Apply thin coats and recoat in 30 minutes. Recoat 3 or more times. After each use, clear valve by holding can upside down and spraying until only clear gas comes out. If spray button becomes clogged, wear eye protection, wipe off the button opening with acetone-DO NOT stick pin in spray button opening.

**CLEANUP:** Use acetone for clean-up.

**DISPOSAL:** Contact your local environmental regulatory agency for guidance on disposal of empty can. Do not burn or place in home trash compactor.

### **NOT RECOMMENDED FOR EXTERIOR USE.**

**PRECAUTIONS AND FIRST AID:** Sanding and grinding dusts may be harmful if inhaled. In a fire or if heated, a pressure increase will occur and the container may burst or explode. This material increases the risk of fire and may aid combustion. Keep away from heat, sparks and flame. Keep away from flames, such as a pilot light, and any object that sparks, such as an electric motor. Do not puncture or incinerate container. Do not expose to heat or store at temperatures above 120°F. Keep away from combustible material. Do not breathe vapor or mist. Do not swallow. Do not get on skin or clothing. Avoid contact with eyes. Keep container tightly closed and sealed until ready for use. Wash thoroughly after handling. Provide fresh air ventilation during and after application and drying. Avoid the inhalation of dust, particulates, spray or mist arising from the application of this preparation. Use personal protective equipment as required. **DANGER—RAGS, STEEL WOOL OR WASTE SOAKED WITH DEFT WOOD TOUCH-UP/ REPAIR/RESTORATION MAY SPONTANEOUSLY CATCH FIRE IF IMPROPERLY DISCARDED. IMMEDIATELY AFTER EACH USE, PLACE RAGS, STEEL WOOL OR WASTE IN A SEALED WATER-FILLED METAL CONTAINER.** **FIRST AID:** If swallowed, rinse mouth with water (only if the person is conscious). Call physician immediately. Do not induce vomiting unless directed to do so by medical personnel. If in eyes, rinse with water for 15 minutes. Check for and remove any contact lenses. In case of contact,

immediately flush skin with plenty of water while removing contaminated clothing and shoes. Get medical attention immediately. If inhaled, remove to fresh air. Call physician immediately.