

Klean-Strip® Concrete and Metal Prep does the job of three products:

(1) Removes rust from iron and steel surfaces, 2) treats metal surfaces, including galvanized and aluminum, to allow better paint adhesion, and (3) etches concrete to allow paint or stains to penetrate and adhere.

DIRECTIONS FOR USE:

FOR RUSTED SURFACES (To Remove Rust)

1. Remove any oil, grease, & dirt from surface. Remove loose rust with a wire brush.

2. Apply product to affected metal full strength with a paintbrush, spray bottle or pump-up sprayer. Work the solution into rusted areas with a stiff bristle brush and allow product to dry overnight to fully neutralize rust

Rinse or wipe surface with a damp cloth to remove any rust residue.

4. Paint treated surface within 48 hours of application to prevent formation of new rust. Two applications may be necessary to treat severe rust

FOR TREATING METAL FOR PAINTING (Phosphotizing)

Remove any oil, grease, & dirt from surface.

Dilute 1 part product with 3 parts water in a plastic container.

3. Apply product with a paintbrush, spray bottle or pump-up sprayer to metal. Surface may turn gray/white.

4. Thoroughly rinse with water after 15-30 minutes.

5. Wipe off any loose powder that forms. Paint treated surface within 48 hours of application to prevent formation of new rust.

FOR ETCHING CONCRETE (Before Applying a Coating)

1. Concrete must be clean and bare of sealers or coatings.

2. Dilute 1 part product into 4 parts water in a plastic container.

- 3. Apply this dilution evenly, at a rate of 300 sq ft/gallon, using a plastic garden watering can with sprinkling head. Do not pour onto one spot and brush out over surface. Product should begin foaming as it reacts with concrete if no foaming happens concrete is sealed and sealer must be removed.
- 4. Let stand at least 10 minutes and then thoroughly rinse with plenty of clean water, scrubbing lightly with a nylon broom to remove any residue. Allow surface to dry before top coating.

IMPORTANT: Carefully read all directions and cautions prior to use. Only use this product as directed on the label. Do not use for any other purpose and do not mix with any other product such as bleach. Protect hands with chemical-resistant gloves and eyes with chemical splash goggles. Avoid contact with painted surfaces. Avoid ovrspray. Rinse tools with water after use.

DANGER: MAY CAUSE BURNS. SKIN AND EYE IRRITANT. HARMFUL IF SWALLOWED. Contains Phosphoric Acid. Avoid contact with eyes, skin and mucous membranes. Use with adequate ventilation. If breathing difficulty occurs, move to fresh air. Do not take internally. FIRST AID - IF SWALLOWED, do not induce vomiting. Drink 1 or 2 glasses of water and call physician immediately. IN CASE OF EYE CONTACT, immediately flush with water, remove any contact lens and flush with water for at least 15 minutes, then get immediate medical attention. FOR SKIN CONTACT, immediately wash with soap and water. Remove contaminated clothing and wash before reuse. If symptoms persist, get medical attention. KEEP OUT OF REACH OF CHILDREN.