



4 TIERS PERFORATED METAL RACK L600/750/900xW300/350/450xH900/1200/1800mm









1:Screw the adjustable feet to the lower poles.




3: Please make sure that you have the perforated steel shelf the correct way up. Hold the perforated steel shelf on its side and slide the top of the four poles through the bottom of the perforated steel shelf at its corners until there is a snug fit. After the four poles have been slid through the perforated steel shelf corner holes, set the perforated steel shelf upright.




5:Make the upper poles connected with the lower poles and make sure its fastness.



2:Snap the plastic clips into the pole groove of four lower poles at the same position.





4: Repeat the step (2) and the step (3) to assemble the 2nd perforated steel shelf as the photo.




6:Repeat the step(2) and the step(3) to assemble the 3rd and the 4th perforated steel shelf as the photo. Then pushing firmly down on every perforated steel shelf at corners by rubber mallet to sesure the perforated steel shelf in a place over the plastic clips.


5 TIERS PERFORATED METAL RACK L900xW450xH1800mm









1:Screw the adjustable feet to the lower poles.




3: Please make sure that you have the perforated steel shelf the correct way up. Hold the perforated steel shelf on its side and slide the top of the four poles through the bottom of the perforated steel shelf at its corners until there is a snug fit. After the four poles have been slid through the perforated steel shelf corner holes, set the perforated steel shelf upright.



5:Make the upper poles connected with the lower poles and make sure its fastness.



2:Snap the plastic clips into the pole groove of four lower poles at the same position.





4: Repeat the step (2) and the step (3) to assemble the 2nd perforated steel shelf as the photo.




6:Repeat the step(2) and the step(3) to assemble the 3rd and the 4th&5th perforated steel shelf as the photo. Then pushing firmly down on every perforated steel shelf at corners by rubber mallet to sesure the perforated steel shelf in a place over the plastic clips.


3 TIERS PERFORATED METAL RACK L600xW300xH700mm









1:Screw the adjustable feet to the one-pice pole.




3: Please make sure that you have the perforated steel shelf the correct way up. Hold the perforated steel shelf on its side and slide the top of the four poles through the bottom of the perforated steel shelf at its corners until there is a snug fit. After the four poles have been slid through the perforated steel shelf corner holes, set the perforated steel shelf upright.





2:Snap the plastic clips into the pole groove of four one-piece pole at the same position.



4: Repeat the step (2) and the step (3) to assemble the 2nd perforated steel shelf (A) as the photo.

6:Repeat the step(2) and the step(3) to assemble the 3rd perforated steel shelf as the photo. Then pushingfirmly down on every perforated steel shelf at corners by rubber mallet to sesure the perforated steel shelf in a place over the plastic clips.