

Propane Torch for Ice Melt, Weed Removal and Blacktop Repair

Important: Read All Directions Before Using

The propane torch is designed to operate with any standard propane cylinder that uses a CGA600 thread fitting available at most hardware stores. It is to be used outdoors only in well ventilated areas. The propane torch produces very high temperatures and care should always be taken around flammable materials including dry grass, leaves, gas cans and more as they easily pose a fire hazard. Always be aware of where the flame is directed. Always keep the flame pointed toward the ground. Never point the flame toward flammable materials, buildings or people. Be careful not to accidentally touch your shoes with the flame. Follow the instructions on the propane cylinder as to the proper use. Do not store unused cylinders near flame or any source of heat. Do not puncture or incinerate empty cylinders. The nozzle of the propane torch remains hot even after the flame is extinguished. Do not touch the nozzle or place the nozzle into contact with flammable materials.

Instructions for Use:

Turn the gas regulating valve all the way clockwise so that it is in the closed position. Screw the propane tank cylinder on to the propane torch. A small amount of propane might escape while attaching the cylinder. The cylinder is properly attached when all hissing from the cylinder ceases. In the event a tight connection cannot be easily made, use the extra "O" ring (included) to make the secure connection. Open the regulating valve slowly and ignite the propane torch at the nozzle end. Adjust the size of the flame by turning the regulating valve.

To melt ice, kill weeds, repair blacktop or ignite charcoal point the flame of the propane torch at the desired object. Make sure that the propane canister remains in the upright position to prevent flare-ups and possible malfunction during use.

To turn the propane torch off, turn the regulating valve until fully closed. The remaining propane in the torch will burn off in a few seconds and the flame will be extinguished. Remove the propane cylinder when the torch is not in use.



Bare Ground Systems

P.O. Box 3477

Framingham, MA 01701

888-800-8356

www.bareground.com bareground@bareground.com