



ALUMINUM FLOOR TRIMS

Use and Care

1. Wipe down your aluminum floor trim surface with a damp sponge to remove general surface dirt. Dry the aluminum floor trim with a towel to prevent water spotting.
2. Squeeze one or two drops of mild dishwashing detergent into a cup of water. Apply the soapy water to a sponge and clean the surface thoroughly. Aluminum floor trims require a gentle cleaning solution, as many harsh cleaning products may react with the aluminum.
3. Wipe off the aluminum floor trim surface with a damp sponge and then dry it with a towel.