## **Method of Application:**

Do not dilute, use as supplied. Do not apply when surface or air temperature is below  $50\,^{\circ}$ F or if rain is expected within 5 hours.

Shrinkage cracks: (less than 1/32" wide): Prime with Lanco® Acrylic Roof and Wall Primer / Sealer™ AS-210 and let dry. Apply Lanco® Siliconizer Elastomeric Crack Filler™ over crack and two inches to each side of it.

**Cracks 1/32" or bigger:** Any cracks bigger than 1/32" should be pouted out to 1/4" wide and 1/4" deep. Clean crack with water, and let dry. Prime with Lanco® Acrylic Wall and Roof Primer / Sealer™ AS-210 and let dry four hours. Fill joint completely and two inches to each side with Lanco® Siliconizer Elastomeric Crack Filler™ and let dry 24 hours.

**Joints:** Clean joints with water and let dry. Prime with Lanco® Acrylic Roof and Wall Primer / Sealer™ AS-210. And let dry. Fill them with backing rod and cover with Lanco® Siliconizer Elastomeric Crack Filler™ 11/16" over surface and two inches to each side of joint.

Cracks with reinforced mesh: Prime with Lanco® Acrylic Wall and Roof Primer / Sealer™ AS-210 and let dry four hours. Fill joint completely and two inches to each side with Lanco® Siliconizer Elastomeric Crack Filler™ to surface. Embed fiberglass fabric into the wet mastic using a soft knife or spatula using sufficient pressure to force mesh into wet mastic through the mesh openings and around fabric strands. Conform the fabric uniformly to the surface. Avoid over stretching, bridging or "fish-mouths" in fabric. Apply a final coat of liquid mastic over entire surface ensuring fabric mesh is not visible and let dry.

**Thinning:** Thinning is not recommended.

**Precaution:** Do not apply when air or surface temperature is below  $50\,^{\circ}\text{F}$  ( $10\,^{\circ}\text{C}$ ). Apply liberally, but do not overspread. Stop painting at least two hours before you expect dew to form or the temperature to fall below  $50\,^{\circ}\text{F}$  ( $10\,^{\circ}\text{C}$ ).

## Additional Information:

**Caution:** Harmful if swallowed. Contains acrylic resin. In case of eye contact, flush thoroughly with water. Do not rub eyes. In case of skin contact, flush area immediately with clean water. If swallowed, do not induce vomiting. Consult a physician immediately. Use only with adequate ventilation. Adequate ventilation required when sanding or abrading the dried film. Always use (NIOSH/MSHA TC21C or equivalent.) Goggles are recommended while handling the product. This product may contain chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. Keep out of reach of children.

**Warning!** If you scrape, sand, or remove old paint, you may release lead dust. Lead is toxic. Exposure to lead dust can cause serious illness, such as brain damage, especially in children. Pregnant women should also avoid exposure. Wear a NIOSH-approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead. For chemical emergency call ChemTrec 1-800-424-9300. Protect from freezing.

<sup>•</sup> CARIBBEAN & SOUTH AMERICA • Urb. Aponte #5, San Lorenzo, Puerto Rico USA 00754 • Tel. (787) 736-4221 Fax (787) 736-5313

<sup>•</sup> CENTRAL AMERICA • Zona Industrial Bes, lote #4, El Coyol de Alajuela, Costa Rica • Tel. (506) 2438-2257 Fax (506) 2438-2162