


) TROUBLESHOOTING

PROBLEM		CORRECTION	WHOLE HOUSE WATER FILTER SYSTEM
No water flow	~	 Re-read the instructions to install the system properly. Check the in and out arrows on the bypass valve to ensure the system is not piped backwards. Make sure the bypass valve is in the "Service" position. 	Whole House Water Filter Systems
Media discharging during backwash	 	• Make sure top distributor has been installed properly.	Whole House Water Filter Systems
System does not backwash	 	 Control valve not programmed properly. Check programming and re-program as needed. 	Whole House Water Filter Systems
Poor performance (filtration)		 Check the frequency and period of backwashing. 	Whole House Water Filter Systems
Leak in distributor tube	~	• Put the system in bypass position and depressurize* the unit by putting into "Backwash" position.	Whole House Water Filter Systems



After prolonged periods of non-use (such as during a vacation), it is recommended that the system be flushed thoroughly. 1. First put the system in bypass by turning the bypass valve to the "BYPASS" position.

2. Let water run for 10-20 minutes by opening all faucets to flush all water supply lines. 3. Turn handle on bypass valve to "SERVICE" position to backwash* the system.

*To backwash or depressurize the system, refer to "Programming Automatic Control Valve" in manual.