

Find the surface you're masking or adhesion level. When more than one tape is recommended, consider application conditions and removal time to determine the right tape for the project.

		SCOTCH® MASKING TAPE			
		Performance Painting #2050	General Purpose #2020	Humid Conditions #2045**	Concrete, Brick & Grout #2060
ADHESION LEVEL		Medium-High	High	High	Very High
	Adhesive	Rubber	Rubber	Rubber	Rubber
	Backing	Crepe	Crepe	Crepe	Crepe
COATED SURFACES					
	Enamel, Varnish or Acrylic on Wood or Metal	•	•	•	•
	Lacquer on Wood, Trim, Metal or Hardware	•	•	•	•
	Finished Hardwood Floors*	•	•	•	•
	Anodized Aluminum, Enameled, Clear or Powder-Coated Metal, Doors, Fixtures, Hardware, Siding and Windows	•	•	•	•
	Painted Wallboard – Smooth to Semi-Smooth	•	•	•	•
	Wood Siding/Clapboard (non-rough)	•	•	•	•
	Fresh Paint (24 hours old)	•	•	•	•
	Cured Paint (24 hours–14 days old; fully cured per paint manufacturer's recommendation)	•	•	•	•
	Primed Metal, Wood and Drywall	•	•	•	•
	Low-VOC/Hard-to-Stick-to Paints	•	•	•	•
NON-COATED SURFACES					
	Cabinets – Veneer	•	•	•	•
	Wallcoverings – Solid Vinyls	•	•	•	•
	Wallpaper – Vinyl Coated Papers	•	•	•	•
	Carpet and Fabric	•	•	•	•
	Caulk (cured until firm)	•	•	•	•
	Brick, Concrete, Grout, Mortar, Stucco and Wood (rough)	•	•	•	•
	Glass, Laminates, Metals (uncoated), Plastics, Solid Surfaces and Wood (smooth)	•	•	•	•
	Vinyl – Base Molding	•	•	•	•
	Vinyl – Window and Door Trim, Floors and Siding	•	•	•	•
COATING BEING APPLIED					
	Water- or Oil-Based	•	•	•	•
	Lacquer- or Solvent-Based Coating	•	•	•	•
APPLICATION CONDITIONS					
	Normal (50°F–100°F)	•	•	•	•
	Warm (100°F–120°F)	•	•	•	•
	Elevated Humidity	•	•	•	•
	INTERIOR CLEAN REMOVAL TIME (days)	5	3	5	3
	EXTERIOR CLEAN REMOVAL TIME (days)	1	1	3	3
SUPER SHARP PAINT LINES					



*Polyurethane floor coatings may be improperly applied and marginally bonded to the underlying stained wood. These coatings can be lifted when tape is removed. Test before use.
 **Available in 2017.