Blinds & Shades Measuring Guidelines

Inside Mount

Blinds/Shades are mounted inside the window casing/frame. Use a metal measuring tape (cloth tapes may stretch).

Measure the inside width of the window opening in 3 places; top, middle and bottom. (Fig A)

Record the <u>widest</u> measurement.



Measure the inside height of the window opening in 3 places; let, middle and right. (Fig B)

Record the **longest** measurement.



*Note:


Measure exactly to the nearest 1/16 in., do not make any deductions or allowances. Use these recorded measurements to select the appropriate blinds/shades for your window opening. Do not order blinds/shades shorter than your window opening.

Outside Mount

Blinds/Shades are mounted outside the window casing/frame. Use a metal measuring tape (cloth tapes may stretch).


Measure the <u>exact</u> <u>width</u> of the entire area to be covered.

For added light control and privacy, suggest to add 1 ½" on each side.



Measure the <u>exact</u> <u>height</u> of the entire area to be covered.

For added light control and privacy, suggest to add 1 ½" to the height.



*Note:

Measure exactly to the nearest 1/16 in., do not make any deductions or allowances.

Select the width and height closest to the area you want to cover.

Do not order blinds/shades less than the area you want to be covered.

For better light and privacy control, approximately 3" for overall width and 3" for overall height.