
PARTS DIAGRAM



PARTS LIST

Item#	Description	Quantity		
1	Frame	2		
2	Base	2		
3	Supporting Arm	2		
4	Extended Arm	2		
5	Parallel Support Frame	2		

HARDWARE LIST

Part	Description	Pic.	Quantity	Part	Description	Pic.	Quantity
Α	M12*75 Hexagon Bolt	1	2	J	16-U Bolt		2
В	Stop Bolt	N.	2	K	M12*30 Hexagon Bolt	1	2
С	12-U Bolt		4	L	M12 Locknut	The second se	6
D	M12 Nut	0	2	М	M12 flat washer	0	1
E	M12 Spring Washer	C	2	N	Ladder Stop		1
F	M12X185 Socket Head Screw Bolt	ľ	4	0	Tie Down Ring	0-	2
G	M12*60 Hexagon Bolt	A l	6	Р	M6 Washer	0	4
н	M16 Nut	0	2	Q	M6 Lock Nut		2
Ι	M16 Spring Washer	C	2				

201707