



# SALTA

---


2 SEAT SOFA / 3 SEAT SOFA



442262.442262



442262.442262.442262











  AMERICA  
 EUROPE  
- Geprüfte Sicherheit  
- EN 581












  
**MAX** 110 kg  
240 lbs

< 40 °C < 104 °F  
> 0 °C > 32 °F




		
RS 	1x	1x
LS 	1x	1x
LSC 	1x	1x
RSC 	1x	1x
S 	2x	3x


		
<p>B </p>	2x	3x
<p>ML </p>	1x	2x
<p>L </p>	4x	4x
<p>M </p> 	33x	46X +9 Extra
<p>Z </p>	1x +2 Extra	1x +4 Extra




1




2




3





4







5 — 13








14 — 22






6




7







8




9




10





11




12




13







15




16




17




18




19



20



21



22



